

Condor Pacific

Gyro Manufacture Repair Overhaul

CPI Rate Gyro

Turn Rate Transmitter (TRU-2A/A) Compliant to MIL-T-27200C

- NSN 6615-01-256-9474
- PN 11700

Applications include C-130, F-16, T-38, F-5, UH-60, SH-60, as well as many other military aircraft.

Flight Control Systems Gyroscope for the CH-53 helicopter

- NSN 6615-01-063-2830
- Sikorsky PN 65901-02003-102
- PN 11000

Flight Control Systems Gyroscope for the F-4 aircraft

- NSN 6615-01-054-6075 PN 12000
- NSN 6615-01-052-0422 PN 12020
- NSN 6615-01-052-0423 PN 12040

Flight Control Systems Gyroscope for the F-5 and T-38 aircraft

- NSN 6615-01-099-8897
- PN 20110 (PN 20110 is an upgrade to PN 20100)
- The first Qualification Test Report (QTR) on the F-5 and T-38 was completed in 1962

Rate of Turn Indicator

- Bell Helicopter PN 214-075-244-101
- PN 11760



Condor Pacific Industries, Inc.

905 Rancho Conejo Blvd, Newbury Park, CA 91320

Phone: 818-889-2150 FAX: 818-889-2160 E-mail: sales@condorpacific.com

Cage Code 4LSH0